

General Tolerances		Linear dimension																Radius, chamfer				Angle (nominal dimension=short side)				Form tolerances: Surface area principle		
Plastic parts	Nominal size	above	1	3	6	10	15	22	30	40	53	70	90	120	160	200	250	315	400	0	3	6	0	10	50	120	Position: individual definition	Tolerance: definition
	until	1	3	6	10	15	22	30	40	53	70	90	120	160	200	250	315	400	3	6	10	50	120	400				
	Tolerance		+ 0.10	+ 0.11	+ 0.12	+ 0.14	+ 0.17	+ 0.20	+ 0.24	+ 0.28	+ 0.33	+ 0.40	+ 0.50	+ 0.60	+ 0.75	+ 0.95	+ 1.15	+ 1.45	+ 1.80	+ 0.20	+ 0.50	+ 1.00	+ 1°	+ 0°30'	+ 0°20'	+ 0°10'		